

BANKSIA CANDLE BANKSIA
Banksia attenuata

Generally good condition, requiring clean
up and crown lift if required.

SHEOAK

COMMON SHEOAK
Allocasuarina fraseriana

TUART

Generally good condition, some marked poor or dead have evidence of die buck present, limit access below, 8 x large sentinel trees (habital specimens, x Marked Feature tuart), and usulable for shade tree adjacent playspaces.

TUART

TUAR

PP POWER POLE

SP STAY POLE

SW STAY WIRE

HYD HYDRANT

MHS WATER CORP MANHOLE

NOTES:

1: THIS DRAWING AND THE CONCEPTS WITHIN WILL REMAIN THE PROPERTY OF ESCAPE LANDSCAPE ARCHITECTURAL DESIGN & CONSTRUCTION PTY LTD. THEY SHALL NOT BE COPIED OR LENT WITHOUT PRIOR CONSENT OF ESCAPE LANDSCAPE ARCHITECTURAL DESIGN & CONSTRUCTION PTY LTD.

2: CONTRACTORS TO CHECK ALL MEASUREMENTS ON SITE PRIOR TO COMMENCMENT OF WORKS.

3: CONTRACTORS TO CONFIRM DESIGN CHANGES & DISCREPANCIES WITH THE SUPERINTENDENT PRIOR TO COMMENCEMENT OF WORKS.



DRAWN N.CROWE

SCALE 1:750 @ A1

DATE 11.04.2019

CLIENT TIM MARSHALL

LANDSCAPE ARCHITECT

A1 DRAWING NO. LC-01

REV