



SCALE 1:250 AT ORIGINAL SIZE



NOTES:

1. AERIAL PHOTOGRAPH PROVIDED BY CITY OF WANNEROO, TAKEN IN OCTOBER 2018.

PROS

 LIMITED EXTENT OF VEGETATION CLEARING & EARTHWORKS REQUIRED. • TIE IN WELL WITH EXISTING PATHWAY. SIMPLEST TO CONSTRUCT. • LOWEST COST.


CONS


 NO ADDITIONAL BUFFER AGAINST CONTINUED BEACH AND DUNE EROSION.

SCALE AT A3 AS SHOWN MARCH 2019

SK1637-01C

P:\MRA Paying Jobs\K1637 CoW Claytons Beach Access\5 MRA Dwgs\Sketches\190319 SK1637 MASTER Rev C







SCALE 1:250 AT ORIGINAL SIZE

1. AERIAL PHOTOGRAPH PROVIDED BY CITY OF WANNEROO, TAKEN IN OCTOBER 2018.

 STAIR TOE LOCATED SLIGHTLY FURTHER LANDWARD. SOME BUFFER AGAINST CONTINUED BEACH AND DUNE

MINIMAL CHANGE TO EXISTING ACCESS.

 VEGETATION CLEARANCE & EARTHWORKS REQUIRED. • INCREASED COST COMPARED TO OPTION 1. INCREASED PILING AND JOINING WORKS.

INDICATIVE ROCK LEVEL TO BE CONFIRMED BY GEOTECHNICAL INVESTIGATION

MARCH 2019

AS SHOWN

SK1637-02C

P:\MRA Paying Jobs\K1637 CoW Claytons Beach Access\5 MRA Dwgs\Sketches\190319 SK1637 MASTER Rev C